

Update AT2000STC

Update Heater regarding new altitude function
with new Software / Parameter – Set

Which heaters can be updated?

Heater version:	Ident. No. Heater Old	Ident. No. Heater New	Ident. No. EOL Old	Ident. No. EOL New
AT2000STC MAM 12VD	9031180B	9031180C	1323353C03 1323353C04	1323353D05
AT2000STC MAM 12VB	9031179B	9031179C	1323351C03 1323351C04	1323351D05
AT2000STC MAM 24VD	9031178B	9031178C	1323165C03 1323165C04 1323165C05	1323165D06

After flashing visible in diagnosis
report !

New configuration:

- Software Tool „WBupdate“ V1.10 is used for update
- It is necessary to rename the Update program from .txt to .exe

See document “*WB_Update Instructions_EN*”

Please note while flashing

- It is not allowed to interrupt the power supply!
→ otherwise the ECU will get damaged and has to be substituted
- The power supply has to be proper
→ use a power supply 12/24V / >10A or well charged 12/24V battery
- Close all other programs (Office...) and stop background tasks (network connections, anti-virus software, screen saver...)
- Check proper installation of all electrical connections

Please note:
flashing only with USB

Which new / changed functions include the update

- new altitude function / only available in combination with Multicontrol