

AirTop-Evo40-55

Update Heater regarding failure F97h

with new Parameter – Set

Which heaters can be updated?

Ident Number	Description
9027500D	Heater AT EVO 40 B 12V STD
9027516D	Heater AT EVO 40 D 12V STD
9027517E	Heater AT EVO 40 D 24V STD
9027518E	Heater AT EVO 55 B 12V STD
9027519E	Heater AT EVO 55 D 12V STD
9027520E	Heater AT EVO 55 D 24V STD
9027521C	Heater AT Evo 40 D 12V STD No DP-Cable
9027522D	Heater AT EVO 40 D 24V SPM No DP-Cable
9027523D	Heater AT EVO 55 D 12V STD No DP-Cable
9027524D	Heater AT EVO 55 D 24V STD No DP-Cable
9027525C	Heater AT Evo 40 D 12V Ambulance
9027526D	Heater AT Evo 55 B 12V Ambulance
9027527D	Heater AT Evo 55 D 12V Ambulance

New configuration:

- Software Tool „Wbup_date“ V1.10 is used for update
- It is necessary to rename the Update program from .txt to .exe

Please note while flashing

- It is not allowed to interrupt the power supply!
→ otherwise the ECU will get damaged and has to be substituted
- The power supply has to be proper
→ use a power supply 12/24V / >10A or well charged 12/24V battery
- Close all other programs (Office...) and stop background tasks (network connections, anti-virus software, screen saver...)
- Check proper installation of all electrical connections

Please note:
flashing only with USB

Which new / changed functions include the update

- new parameter set for failure F97h